





FOR SHEET 1 OF THIS DRAWING SEE DL11-302.1-0500 ALL DIMENSIONS IN CENTIMETRES UNLESS OTHERWISE STATED

02	FEB 2022	GENERAL UPDATE TO PARTS, LAYOUTS AND NOTES. UPDATED CENTRE-PHASE SURGE ARRESTER CONNECTION AND ORIENTATION. REMOVED OLD NOTE 2. UPDATED NEW NOTES 1, 2 & 12. ADDED NEW NOTES 13 & 15 & 16. CHANGED 'D2' TO 'FIG.2' AND REFERENCED MAIN LAYOUT AS 'FIG.1'.	PC	ММ		ММ
01	NOV 2018	ORIGINAL DL11-304.3-R2 & DL11-304.4-R2 ARE SUPERSEDED BY THIS NEW DRAWING/REVISION. GENERAL UPDATES & DRAWING TILE EDIT. CHANGED TO NEW DWG. & NUMBERING FORMAT.	SO	PC	ММ	DD
Rev No	Date	Revision Particulars	dwn	ckd	des	ann

Hydro One Networks Inc.

Information contained in this drawing is considered to be confor its intended purpose and shall take necessary measures to p

LEGEND:	
•	- IN-LINE DISCONNECT SWITCH (SOLID BLADE)
	SURGE ARRESTER
<u>•</u>	BONDING/GROUNDING
-	INSTRUMENT (CURRENT) TRANSFORMER
-80-	INSTRUMENT (VOLTAGE) TRANSFORMER

PART No.		PARTS LIST	
	MM No.	DESCRIPTION	Q٦
1	MM#	CONNECTOR, LIVE LINE	6
2		CROSSARM, COMPOSITE, TANGENT, 9'-6"	
3	30000770	CLAMP REST, INSULATOR TYPE	6
4			1
	30008425	BRACKET, CLAMP REST, T-TYPE INSULATOR, STANDOFF, 28kV OR	
5		INSULATOR, STANDOFF, 44kV	7
6	MM#	BOLT, 3/4"	A/
		SWITCH - IN-LINE (BY-PASS)	
7	MM#	28kV OR 46kV, 900A, WEDGE-TYPE	Α/
8	MM#	CONDUCTOR, BARE COPPER	A/
9	MM#	CONNECTOR, TAP, WEDGE-TYPE	A
	30008430	INSULATOR, LP28 WITH CLAMP OR	
10		INSULATOR, LP46 WITH CLAMP	;
11	Δ	BONDING LUG, MODULAR METERING	-
		ARRESTER, DISTRIBUTION, FOR 26.4kV	
12		ARRESTER, INTERMEDIATE, FOR 44kV	3
13		BRACKET, SURGE ARRESTER, INTERMEDIATE	3
	30013233	MODULAR METERING UNIT (CT/VT),	
14	SEE NOTE 4	2-ELEMENT	1
15	30001595		A/
16	100001095	WASHER, 3/4" x 2" x 2" LOCKWASHER, 3/4"	A/
		NAIL, 1–3/4" LONG, GALV.	
17	30001734	WITH NEODDENE WASHED	A,
10	70000745	WITH NEOPRENE WASHER	A
18	30000745	STRAP, PIPE, 1", 2-HOLE	A,
19	MM#	BOLT, 5/8"	A,
20	30000346		
21	SEE NOIE 4	METER ENCLOSURE	
22	30001594	WASHER, 5/8" x 2" x 2"	A,
23	SEE NOTE 4	REVENUE METER	1
24	20002145	SIGN, "KEEP OUT"	
25	30034591	MOULDING, GROUND WIRE STAPLE, 3", MOULDING	A/
26	30013378	STAPLE, 3", MOULDING	Α,
27	30000905	STUD, INSULATOR, 3/4" x 3" STUD, INSULATOR, 3/4" x 7"	
28	30000906	STUD, INSULATOR, 3/4" x 7"	2
29	30000800	BRACKET, POLE TOP	
30	мм#	STIRRUP	(
31	Δ	BONDING LUG, METER ENCLOSURE	_
32	30006856	STUD, LIVE LINE	A,
33	30021308	BRACKET, MOUNTING, FOR P-BASE	
	100021000	METER SUPPORT, C/W HARDWARE	
34	Δ	CONNECTOR, BOX, 1, CONDUIT	2
34 35	Δ	CONNECTOR, BOX, 1, CONDUIT	Ź A,
34 35 36	∆ 30026619	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE	A,
34 35 36 37	∆ 30026619 MM#	CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8"	A,
34 35 36 37 38	△ 30026619 MM# 30034307	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG	A,
34 35 36 37 38 39	△ 30026619 MM# 30034307 30007243	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS	A, A, A,
34 35 36 37 38	△ 30026619 MM# 30034307 30007243	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED	A, A, A,
34 35 36 37 38 39	△ 30026619 MM# 30034307 30007243	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE-TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF-TAPPING, HWH, 2"	A, A, A, A,
34 35 36 37 38 39 40	△ 30026619 MM# 30034307 30007243 30001613	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE-TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF-TAPPING, HWH, 2"	A, A, A, A, A,
34 35 36 37 38 39 40 41	△ 30026619 MM# 30034307 30007243 30001613 30032211	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE-TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF-TAPPING, HWH, 2"	A, A, A, A, A,
34 35 36 37 38 39 40 41 42	△ 30026619 MM# 30034307 30007243 30001613 30032211 30024726	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED	A, A
34 35 36 37 38 39 40 41 42 43	△ 30026619 MM# 30034307 30007243 30001613 30032211 30024726 30025578 30030842	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC	A, A, A, A, A, A, A,
34 35 36 37 38 39 40 41 42 43	△ 30026619 MM# 30034307 30007243 30001613 30032211 30024726 30025578	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE-TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF-TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE,	A/ A/ A/ A/ A/ A/ A/
34 35 36 37 38 39 40 41 42 43 44	△ 30026619 MM# 30034307 30007243 30001613 30032211 30024726 30025578 30030842 30006969	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE	A,
34 35 36 37 38 39 40 41 42 43	△ 30026619 MM# 30034307 30007243 30001613 30032211 30024726 30025578 30030842	CONNECTOR, BOX, 1, CONDUTI CONDUTI, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION	A,
34 35 36 37 38 39 40 41 42 43 44	△ 30026619 MM# 30034307 30007243 30001613 30032211 30024726 30025578 30030842 30006969 MM#	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU,	A, A
34 35 36 37 38 39 40 41 42 43 44 45	△ 30026619 MM# 30034307 30007243 30032211 30024726 30025578 30030842 30006969 MM# 30013881	CONNECTOR, BOX, 1, CONDUTI CONDUTI, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION	A/A/A/A/A/A/A/A/A/A/A/A/A/A/A/A/A/A/A/
34 35 36 37 38 39 40 41 42 43 44 45 46	△ 30026619 MM# 30034307 30007243 30001613 30024726 30025578 30030842 30006969 MM# 30013881 30026618	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE	A, A
34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49	△ 30026619 MM# 30034307 30007243 30001613 30032211 30024726 30030842 30006969 MM# 30013881 30026618 △	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS	A/ A/ A/ A/ A/ A/ A/ A/ A/ A/
34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50	△ 30026619 MM# 30034307 30007243 300032211 30024726 30025578 30030842 30006969 MM# 30013881 30026618 △ 30035285	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS CONNECTOR, BOX, 1/2", CABLE GLAND, 10—14mm	A, A
34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51	△ 30026619 MM# 30034307 30007243 30001613 30024726 30025578 30030842 30006969 MM# 30013881 30026618 △ 30035285	CONNECTOR, BOX, 1, CONDUTI CONDUT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS CONNECTOR, BOX, 1/2", CABLE GLAND, 10—14mm BUNDLED CONDUCTORS, #12, 600V	A, A
34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52	△ 30026619 MM# 30034307 30007243 30001613 30024726 30025578 30030842 30006969 MM# 30013881 30026618 △ 30035285 △ △	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/OAWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS CONNECTOR, BOX, 1/2", CABLE GLAND, 10—14mm BUNDLED CONDUCTORS, #12, 600V MARSHALLING BOX	A, A
34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53	△ 30026619 MM# 30034307 30007243 300032211 30024726 30025578 30030842 30006969 MM# 30013881 30026618 △ 30035285 △ △	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, ISEMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS CONNECTOR, BOX, 1/2", CABLE GLAND, 10—14mm BUNDLED CONDUCTORS, #12, 600V MARSHALLING BOX NEMA 4 PADDLE FOR HI & H2 BUSHINGS	A, A
34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52	△ 30026619 MM# 30034307 30007243 30001613 30024726 30025578 30030842 30006969 MM# 30013881 30026618 △ 30035285 △ △ △ 30001166	CONNECTOR, BOX, 1, CONDUTI CONDUT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS CONNECTOR, BOX, 1/2", CABLE GLAND, 10—14mm BUNDLED CONDUCTORS, #12, 600V MARSHALLING BOX NEMA 4 PADDLE FOR H1 & H2 BUSHINGS BOIT, 1/2", 1—1/2" LONG, GALV. OR	A, A, A, A, A, A, A, A, A, A, A, A, A, A
34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53	△ 30026619 MM# 30034307 30007243 30001613 30024726 30025578 30030842 30006969 MM# 30013881 30026618 △ 30035285 △ △ 30001166 30001166	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/OAWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS CONNECTOR, BOX, 1/2", CABLE GLAND, 10—14mm BUNDLED CONDUCTORS, #12, 600V MARSHALLING BOX NEMA 4 PADDLE FOR HI & H2 BUSHINGS BOLT, 1/2", 1—1/2" LONG, GALV., OR BOLT, 1/2", 2" LONG, GALV.	A, A
34 35 36 37 38 39 40 41 42 43 44 45 46 47 48 49 50 51 52 53 54	△ 30026619 MM# 30034307 30007243 30001613 30024726 30025578 30030842 30006969 MM# 30013881 30026618 △ 30035285 △ △ 30001166 30001166	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/OAWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS CONNECTOR, BOX, 1/2", CABLE GLAND, 10—14mm BUNDLED CONDUCTORS, #12, 600V MARSHALLING BOX NEMA 4 PADDLE FOR HI & H2 BUSHINGS BOLT, 1/2", 1—1/2" LONG, GALV., OR BOLT, 1/2", 2" LONG, GALV.	A, A
34 35 36 37 38 40 41 42 43 44 45 46 47 48 49 50 51 51 52 53 54 55	△ 30026619 MM# 30034307 30007243 30001613 30032211 30024726 30025578 30030842 30006969 MM# 30013881 30026618 △ △ △ 30035285 △ △ 30001166 30001157 30001591	CONNECTOR, 17, FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS CONNECTOR, BOX 1/2", CABLE GLAND, 10—14mm BUNDLED CONDUCTORS, #12, 600V MARSHALLING BOX NEMA 4 PADDLE FOR H1 & H2 BUSHINGS BOLT, 1/2", 1—1/2" LONG, GALV., OR BOLT, 1/2", 2" LONG, GALV. WASHER, 1/2", GALV.	A, A
34 35 36 37 38 40 41 42 43 44 45 46 47 48 49 50 51 52 52 53 54 55 56 57	Δ 30026619 MM# 30034307 30007243 30001613 30024726 30025578 30030842 30030842 30013881 30026618 Δ 30035285 Δ Δ 30001166 30001157 30001591 30001605 30007505	CONNECTOR, BOX, 1, CONDUIT CONDUIT, 1", FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, ERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS CONNECTOR, BOX, 1/2", CABLE GLAND, 10—14mm BUNDLED CONDUCTORS, #12, 600V MARSHALLING BOX NEMA 4 PADDLE FOR H1 & H2 BUSHINGS BOLT, 1/2", 1—1/2" LONG, GALV., OR BOLT, 1/2", 2" LONG, GALV. WASHER, 1/2", GALV. WASHER, 1/2", GALV. LOCKNUT, CONDUIT, STEEL, 1/2"	A, A
34 35 36 37 38 40 41 42 43 44 45 46 47 48 49 50 51 52 52 53 54 55 56 57	Δ 30026619 MM# 30034307 30007243 30001613 30024726 30025578 30030842 30030842 30013881 30026618 Δ 30035285 Δ Δ 30001166 30001157 30001591 30001605 30007505	CONNECTOR, 17, FLEX BEARING PLATE, CROSSARM, FOR COMPOSITE POLE LOCKWASHER, 5/8" CONDUCTOR, CCS, 2/0 AWG CONNECTOR, WEDGE—TYPE, FOR 2/0AWG CCS WASHER, 3/4" x 4" x 4", CURVED SCREW, SELF—TAPPING, HWH, 2" STRAP, PIPE, 1/2", 2—HOLE CONDUIT, 1/2", PVC TIE—WRAP, UV RESISTANT, 7.7mm x 370mm CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, LIVE—LINE, PIGTAIL, WEDGE—TYPE CONNECTOR, TERMINAL, COMPRESSION 2—HOLE, SIZED TO SUIT CONDUCTIVITY, CU, STAPLE, GROUND WIRE, 1—1/2" x 3/8" BEARING PLATE, BRACKET, FOR COMPOSITE POLE BACK TO BACK LARGE WASHERS CONNECTOR, BOX 1/2", CABLE GLAND, 10—14mm BUNDLED CONDUCTORS, #12, 600V MARSHALLING BOX NEMA 4 PADDLE FOR H1 & H2 BUSHINGS BOLT, 1/2", 1—1/2" LONG, GALV., OR BOLT, 1/2", 2" LONG, GALV. WASHER, 1/2", GALV.	A, A

Drawn By: SO	Checked By: PC		Design Approved By: D.DESROSIERS
Scale: N.T.S.	Date: (yyyy/mm/dd) 2018/09/20	Pole ID:	
Title			

RETAIL METERING

50

SUBTRANSMISSION 3-PH 3-WIRE (2-ELEMENT) 27.6kV AND 44kV

Rev. No. DL11-302.1-0501 02